

# 42MX Family Devices Power-Up Behavior

## Introduction

Actel antifuse FPGA families offer the advantage of nonvolatility by attaining immediate functionality at power up. Since the programmed design is retained, there is no requirement for additional configuration devices. This application note discusses the results of the 42MX device power-up characterization in detail and recommends appropriate power-up sequences and ramp rates. Tristate behavior of the device I/Os during the power-up cycle offers the flexibility of applying voltages to the I/Os during power-up.

The characterization measurement was carried out in a laboratory environment and the reported data are typical. Hence, the maximum and minimum values under worst and best condition are not guaranteed.

## Background

For 42MX devices manufactured before April 1999, the I/Os would go incorrectly into tristate mode under certain power-up conditions. In an effort to resolve this problem, Actel has created an updated set of 42MX devices, designated by "X39" in their part number. For more information, please refer to the following GURU documents:

<http://www.actel.com/apps/guru/apr99/ns845.html>  
<http://www.actel.com/apps/guru/jul99/ns842.html>

This application note includes the characterization reports for both old and new versions of the 42MX family and is a general source for all 42MX devices.

All 42MX devices have two power supplies:  $V_{CCA}$  and  $V_{CCI}$ , and they can operate in 5V only, 3.3V only, and 5V/3.3V mixed systems. Table 1 summarizes the voltage levels of these power supplies and the corresponding I/O voltage level.

**Table 1 • Power Supply Levels for Different Operations**

$V_{CCA}$	$V_{CCI}$	Input	Output
5V	5V	5V	5V
3.3V	3.3V	3.3V	3.3V
5V	3.3V	3.3V, 5V	3.3V

As seen from Table 1,  $V_{CCA}$  also acts as an input tolerance voltage while  $V_{CCI}$  is used as an I/O module voltage. In single voltage operations,  $V_{CCA}$  and  $V_{CCI}$  are usually tied to each other but for the mixed 5V/3.3V systems ( $V_{CCA}=5V$  and  $V_{CCI}=3.3V$ ),  $V_{CCA}$  must be greater than or equal to  $V_{CCI}$  throughout the power-up sequence. Hence,  $V_{CCA}$  must always be powered up before  $V_{CCI}$  to avoid excessive currents and/or damage to the device.

If  $V_{CCI}$  is 0.5V greater than  $V_{CCA}$  when both are above 1.5V, then the input protection junction on the I/Os will be forward biased, causing them to draw large amounts of current. When  $V_{CCA}$  and  $V_{CCI}$  are in the 1.5V to 2.0V region and  $V_{CCI}$  is greater than  $V_{CCA}$ , all I/Os would momentarily behave as outputs that are in a logical high state, and  $I_{CC}$  rises to high levels.

## Transient Current

Due to the internal logic switching simultaneously during the power-up sequence, a relatively large transient current appears on the I/Os. The amount and duration of this transient current is critical for protecting the board from any possible damages. The transient current is dependent on the  $V_{CCA}$  voltage level (3.3V or 5V) and its ramp rate during power-up. Since the transient current is not due to I/O switching, its value and duration is independent of the  $V_{CCI}$  level.

Transient current measurements are taken for three different operating conditions:

- 5V only:  $V_{CCA}=V_{CCI}=5V$
- 3.3V only:  $V_{CCA}=V_{CCI}=3.3V$
- Mixed 5V/3.3V:  $V_{CCA}=5V$  (powered up first),  $V_{CCI}=3.3V$  (powered up second)

Different ramp rates have been applied to the power supplies. Additionally, in the mixed voltage operation condition, different delays between  $V_{CCA}$  and  $V_{CCI}$  have been tested ranging from 100 $\mu$ s to 250ms. Table 2 and Table 3 on page 2 indicate the amount of the transient current peak in single voltage operation conditions for X39 and non-X39 series, respectively.

It can be derived from the measured data that, the average pulse width of the transient current spike is 350ns with its value increasing as the power supply ramp rate increases. The transient current peak value is also related to the number of logic modules in the device, meaning that larger

devices show a higher transient current. For instance, for all of the X39 series tested devices, 42MX36 has a higher transient current than 42MX24, which in turn, has a higher transient current than 42MX16. However, for the non-X39 measured devices, some discrepancies can be observed. These discrepancies can be seen in [Table 2](#) and [Table 3](#).

The transient currents were reduced with the slower ramp rates. [Figure 1](#) shows the relation between the ramp rates and the transient current peak for the X39 series of 42MX family devices.


For mixed voltage systems, the transient current is very similar to that of the 5V only operation.

**Table 2 • Transient Current for X39 42MX Parts at Different Ramp Rates**

Operating Systems	Products	Transient Current on V <sub>CCA</sub> (mA) at different ramp rates (avg. values)						
		0.5V/ms	0.05V/ms	10V/ms	5V/ms	0.5V/ms	0.2V/ms	0.05V/ms
5V-only systems	42MX16 X39	428	319	255	165	101	95	92
	42MX24 X39	490	465	340	250	130	108	110
	42MX36 X39	539	531	357	346	151	117	112
3.3V-only systems		Transient Current on V <sub>CCA</sub> (mA) at different ramp rates (avg. values)						
	Products	0.33V/ms	0.033V/ms	6.6V/ms	3.3V/ms	0.33V/ms	0.132V/ms	0.033V/ms
	42MX16 X39	196	189	183	148	97	95	90
	42MX24 X39	281	276	265	216	129	113	107
	42MX36 X39	324	327	321	284	124	112	110

**Table 3 • Transient Current for Non-X39 42MX Parts at Different Ramp Rates**

Operating Systems	Products	Transient Current on V <sub>CCA</sub> (mA) at different ramp rates (avg. values)						
		0.5V/ms	0.05V/ms	10V/ms	5V/ms	0.5V/ms	0.2V/ms	0.05V/ms
5V-only systems	42MX16	N/A	N/A	189	140	47	45	43
	42MX24	N/A	N/A	250	234	202	200	197
	42MX36	N/A	N/A	78	64	56	117	108
3.3V-only systems		Transient Current on V <sub>CCA</sub> (mA) at different ramp rates (avg. values)						
	Products	0.33V/ms	0.033V/ms	6.6V/ms	3.3V/ms	0.33V/ms	0.132V/ms	0.033V/ms
	42MX16	184	171	150	114	50	49	85
	42MX24	225	220	208	207	205	199	197
	42MX36	159	89	70	65	55	114	112



**Figure 1 • Transient Current vs. Ramp Rates for MX16, MX24, and MX36 at 5V and 3.3V Operating Conditions**

### I/O Behavior During Power Up

This section discusses the behavior of 42MX device family I/Os during power-up cycles. One of the important parameters during power up is the voltage level at which the I/Os become functional. Since the functionality of I/Os is defined by the time the internal logic is functional, the power up to functional time depends on the ramp rates of  $V_{CCA}$  and not  $V_{CCI}$ . However, the proper data cannot be read from or written into the device unless  $V_{CCI}$  reaches the

value where I/Os become active. After the I/Os become active, there will be some additional delay for the input data to propagate to the output pins. In single-voltage operations, there is only one power supply. Therefore, the power up to functional times and I/O functional times are equal. Table 4 and Table 5 present the power up to functional voltage levels for the single-voltage operation mode.

**Table 4 •  $V_{CCA}$  Voltage where I/Os become Active in 5V-only Operation (V)**

Ramp Rate	0.5V/ms	0.05V/ms	10V/ms	5V/ms	0.5V/ms	0.2V/ms	0.05V/ms
42MX16 X39	5.00	4.65	3.13	2.81	2.41	2.31	2.25
42MX24 X39	5.00	4.81	3.63	3.16	2.41	2.40	2.34
42MX36 X39	5.00	4.91	3.92	3.73	2.54	2.38	2.36
42MX16	N/A	N/A	3.51	2.87	1.90	1.77	1.73
42MX24	N/A	N/A	3.53	3.00	2.55	2.50	2.49
42MX36	N/A	N/A	1.96	1.94	1.86	2.41	2.38

**Table 5 •  $V_{CCA}$  Voltage where I/Os become Active in 3.3V-only Operation (V)**

Ramp Rate	0.33V/ms	0.033V/ms	6.6V/ms	3.3V/ms	0.33V/ms	0.132V/ms	0.033V/ms
42MX16 X39	3.30	3.30	2.88	2.66	2.33	2.30	2.25
42MX24 X39	3.30	3.30	3.19	2.93	2.40	2.34	2.28
42MX36 X39	3.30	3.30	3.30	3.07	2.46	2.41	2.34
42MX16	3.30	3.30	3.01	3.67	1.78	1.76	1.65
42MX24	3.30	3.30	3.11	2.70	2.47	2.43	2.43
42MX36	2.53	2.07	1.91	1.82	1.79	2.38	2.38

Table 4 and Table 5 indicate that the power up to functional voltage level increases for faster ramp rates and larger arrays.

Generally, in a mixed-voltage operation mode, since the array voltage ( $V_{CCA}$ ) is 5V and, as discussed earlier, the power up to functional time depends on the  $V_{CCA}$  ramp-up, Table 4 applies for mixed-voltage mode. However, there are two cases that should be taken into consideration during the power up in a mixed-voltage mode. The first case occurs when the power-up delay between  $V_{CCA}$  and  $V_{CCI}$  is larger than the power-up to functional time. In this case, the internal modules are functional and I/Os are inactive. Therefore, the I/Os' functional time will be defined as the time when  $V_{CCI}$  is powered up. The second case is more critical and happens if the power-up delay between  $V_{CCA}$  and  $V_{CCI}$  is less than the power up to functional time. In other words, it happens when the I/Os are functional but the internal logic modules are not. Thus, the I/Os will be driven to their designated voltage level as soon as the power-up to functional time is reached. In such a condition, there is a short period of time (after I/O activation and before array functionality) that the I/Os might be driven into an unknown state. Hence, it is recommended to power up  $V_{CCI}$  after  $V_{CCA}$  has reached its functional level.

During the characterization procedure, the inputs and outputs of 42MX family devices are tested to determine their behavior during power up, specifically before they become functional. The results of different measurements demonstrate that the I/Os are tristated during the power-up. In other words, a voltage can be applied to a 42MX device I/O before and during power up of the device.

Users should note that for non-X39 devices in 5V-only operation, if the power-up ramp rate of  $V_{CCI}$  is faster than 0.01V/ms, the I/Os will be driven into an unknown tristate mode, and the device will not function properly.

### Conclusion

For proper power up of 42MX family devices,  $V_{CCA}$  should always be greater than  $V_{CCI}$  during power up. In older generations (non-X39) of the 42MX family, there is a power-up rise time restriction to avoid an incorrect tristate on I/Os. This document discussed the transient current on  $V_{CCA}$  and functional voltage level during power-up. The transient current in 42MX devices is reduced by increasing the power-up rise time. For the faster power ups, the voltage level in which the device becomes functional is higher. 42MX device I/Os are also tristated before reaching the functionality point, which makes it possible to apply voltage on I/Os during power up.

Actel and the Actel logo are registered trademarks of Actel Corporation.  
All other trademarks are the property of their owners.



<http://www.actel.com>

**Actel Europe Ltd.**

Maxfli Court, Riverside Way  
Camberley, Surrey GU15 3YL  
United Kingdom

**Tel:** +44 (0)1276 401450

**Fax:** +44 (0)1276 401590

**Actel Corporation**

955 East Arques Avenue  
Sunnyvale, California 94086  
USA

**Tel:** (408) 739-1010

**Fax:** (408) 739-1540

**Actel Asia-Pacific**

EXOS Ebisu Bldg. 4F  
1-24-14 Ebisu Shibuya-ku  
Tokyo 150 Japan

**Tel:** +81-(0)3-3445-7671

**Fax:** +81-(0)3-3445-7668